


# ROOFTOP SURVEYS

We were asked to conduct a High Level survey for building contractor East Kent Property Services on a listed building. It was discovered that render on the high points of the property was coming away from the main structure. Although it was clear from the ground there was a problem it was not possible to determine the exact cause without further inspection.



We inspected the roof using our multi-rotor UAV. Work on site was conducted with the contractor present, and completed in 45 minutes. The images were delivered the same day. The problem was identified and work has now started to rectify it.

**“The pictures supplied were better than a scaffold survey. You can zoom right in and see areas otherwise unreachable. We shall be recommending this service in the future.”**



Pre-Deployment Checks

On Site Within 48 hrs

25 Minute Flight Conducted

Images Delivered On Site

**“To scaffold it would have cost thousands of pounds due to access restrictions. ATEC-3D surveyed the roof for a fraction of the price”**

